

Getting Rid Of the Rubber Plug on a Dana 35

Here is what mine looked like. The rubber plug kept leaking and got oil all over everything



I order 1 ¼" Half coupler Stainless steel and 1 square plug stainless steel from www.MSCdirect.com. Part numbers were 08028979 and 08029761. I could not find a stainless steel ½ coupler from a local store



The diff cover was removed and cleaned. The Half coupler was welded to the diff cover. I used an arc welder since that is all I have.



I applied JB weld over the weld to make sure there were no leaks. I have found that JB works very well when you want air tight welds. It is a lot easier then trying to weld the pin holes closed. The cover was then painted and installed.



John Ruiz

